



**WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN**

9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

No: EST/223/2025

Date: 05.03.2025

NOTIFICATION

As per approval of Hon'ble President , Council , dated: 03.03.2025 E- Tender No. 21/E-Tender/2024-25 , dated: 31.01.2025 , Tender Id No. 2025_DSE_810332_1 , regarding renovation and remodeling work for one room at Kolkata Regional Office of the W.B. Council of H.S. Education , 2nd floor North Block , Bikash Bhavan, Saltlake Kolkata-700091 , has been cancelled due to less number of bidders.

Secretary
W.B. Council of H.S. Education



WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN
9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

Tender Notice No: 21/E- Tender(2nd call)/2024-25

Date: 05.03.2025

QUOTATION NOTICE

Council has decided to invite online quotation from reputed agencies for renovation and remodelling a room of Kolkata Regional Office of the W.B. Council of Higher Secondary Education having its establishment at 2nd floor, North Block of Bikash Bhavan, Salt Lake Kolkata.

Interested agencies are requested to visit Council Website wbchse.wb.gov.in and W.B. Govt Website <https://wbtenders.gov.in> w.e.f. 07/03/2025 for details.

Secretary

W.B. Council H.S. Education



WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN
9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

Tender Form

2024-2025

For RENOVATION AND
REMODELING WORK AT
KOLKATA REGIONAL
OFFICE



WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN
9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

Tender Notice No:21/E-Tender(2nd call)/2024-2025

Date -05/03/2025

Council had decided to for renovation and remodelling a room of Kolkata Regional Office of the W.B. Council of Higher Secondary Education at 2nd floor, North Block of Bikash Bhavan, Salt Lake Kolkata. Online quotations are invited form reputed agencies of West Bengal in this respect, as per following specification.

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of Ground Floor | <ul style="list-style-type: none">- Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the 3 toilets and the adjacent corridor.- Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor.- Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface.- Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc.- Change of damaged water supply pipe lines inside the toilets if necessary.- Change of 3 PVC doors of the toilets.- Change of MS grill gate of the duct.- Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs: |
| Back side toilet of Ground Floor | <ul style="list-style-type: none">- Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor, wall of the toilet in front of back side lift and inside the police room.- Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface.- Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc.- Change of damaged water supply pipe lines inside the toilets if necessary.- Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 1st Floor | <ul style="list-style-type: none">- Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor.- Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor.- Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface.- Change of one wash basin.- Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc.- Change of damaged water supply pipe lines inside the toilets if necessary. | Rs: |

| | | |
|-------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| | <ul style="list-style-type: none"> - Repair and painting of wooden doors of the toilets. - Repair, fixing and painting of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | |
| Back side toilet of 1st Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair and painting of wooden doors of the toilets. - Repair and fixing of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 2nd Floor | <ul style="list-style-type: none"> - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair and painting of wooden doors of the toilets. - Repair and painting of MS grill gate of the duct. | Rs: |
| Back side toilet of 2nd Floor | <ul style="list-style-type: none"> - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair and painting of wooden doors of the toilets. | Rs: |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 3rd Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the 3 toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair and painting of wooden doors of the toilets. - Repair and painting of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs: |
| Back side toilet | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster | |

| | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| of 3rd Floor | <ul style="list-style-type: none"> of ceiling, beams or walls of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. Repair and painting of wooden doors of the toilets. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 4th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair and painting of wooden doors of the toilets. - Repair and painting of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs: |
| Back side toilet of 4th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. Repair and painting of wooden doors of the toilets. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 5th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting | Rs: |

| | | |
|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| | <ul style="list-style-type: none"> plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair of doors the toilets. - Change of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | |
| Back side toilet of 5th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. Change of door of the ladies toilet and repair of other doors of the toilets. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |

| Place of work | Description of Works | Consolidated Rate (Excluding of any tax) |
|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| Front side toilet of 6th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Repair of doors of the toilets. - Change of MS grill gate of the duct. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs: |
| Back side toilet of 6th Floor | <ul style="list-style-type: none"> - Dismantling of burst out conc., and efflorescent plaster of ceiling, beams or walls of the toilets and the adjacent corridor. - Plaster works on ceilings and walls over dado of the toilets and the adjacent corridor, wall of the toilet in front of back side lift. - Painting of two coats of water based acrylic distemper over a coat of primer on the ceiling and walls of toilets, adjacent corridor etc. including preparing surface. - Repair of cisterns, wash basins, urinals, squatting plates etc and the bib cocks, stop cocks etc. - Change of damaged water supply pipe lines inside the toilets if necessary. - Change of existing door of the ladies toilet and repair of other doors the toilets. - Cutting and cleaning of the floor of the toilets and the adjacent corridor. | Rs. |
| Total: Rs. | | |



WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN
9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

-: Terms & Conditions :-

1. a) The Agencies should quote all the item wise rates as mentioned in the tender form.
b) Rates should be exclusive of any taxes.
c) Rates should be quoted in decimal coinage both in figures and in words.
2. Earnest money of Rs.5000.00 to be paid by online Net banking or NEFT/RTGS as per West Bengal Govt. Finance Department order No.3975 – F(Y) dated: 28th July 2016.
3. Agencies shall have to upload the completed tender form along with the following documents.
 - a) Xerox copy of PAN Card.
 - b) Upto-date Professional Tax clearance Certificate.
 - c) Upto-date Trade Licence.
 - d) GST registration certificate.
4. Earnest money of the Agency shall be liable to be forfeited if the Agency withdraws his tender after acceptance of the tender by the Council.
5. Earnest money in respect of the successful Agency will automatically be converted into security deposit which will not carry any interest.
6. Security deposit of the successful Agency will be released after satisfactory execution of the work.
7. The Agency will supply all the necessary materials, equipments, tools and scaffolding for the work.
8. The agency will be fully responsible for any loss, shortage, damage and pilferage of the Council's property during the time of execution of work and the cost of the same as fixed by the Council will be recovered from the bill or Security money as the case may be.
9. The Council will hold no liability for any injury, accident or accidental death etc. for any person which may occur in course of execution of work.
10. The Council also reserves the right to reject any tender or any part thereof at any stage without assigning any reason there for.



WEST BENGAL COUNCIL OF HIGHER SECONDARY EDUCATION
VIDYASAGAR BHAVAN
9/2, Block-DJ, Sector-II, Salt Lake, Kolkata-700091

Date and Time Schedule:

| Sl. No. | Particulars | Date & Time |
|----------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------|
| 1 | Date of uploading of N.I.T. & other Documents (online) (Publishing Date) | 07.03.2025 |
| 2 | Documents download / Sale start date (online) | 07.03.2025 |
| 3 | Bid submission starting date (online) | 07.03.2025 |
| 4 | Bid Submission closing date (online) | 13.03.2025 |
| 5 | Bid opening date for Technical proposal (Folder 1 : Prequalification documents and Folder 2 : Technical submission by bidder) (Online) | 17.03.2025 |
| 6 | Date of uploading list for Qualified Bidder in Technical Proposal | 18.03.2025 |
| 7 | Date for opening of Financial Proposal (online) | 18.03.2025 |

Secretary
W.B. Council H.S. Education